

REPORT OF CHANNEL CONDITIONS 100 TO 400 FEET WIDE <i>(EP 1130-2-520)</i>					PAGE 1 OF 1 <hr/> DATE 23 July 2008		
TO: Navigation Interest				FROM: U.S. Army Engineer District, Baltimore P.O. Box 1715 Baltimore, Maryland 21203-1715			
RIVER/HARBOR NAME AND STATE Baltimore Harbor Baltimore, Maryland					MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD		
NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER <i>(feet)</i>	MIDDLE HALF <i>(feet)</i>	RIGHT OUTSIDE QUARTER <i>(feet)</i>
		WIDTH <i>(feet)</i>	LENGTH <i>(miles)</i>	DEPTH <i>(feet)</i>			
Curtis Bay Channel Station 0+000 to 11+882	18/Jan/200	400	2	50	50	49	48
REMARKS <i>(Continue on reverse)</i> All depths refer to MLLW for the 1983-2001 tidal epoch. This information represents the results of surveys made on the dates shown and can only be as indicating the general conditions at that time. Depths are reported to the nearest foot. Length of channel is reported to the nearest mile (actual length is 2.25 miles). Left Outside Quarter= E1442539.63, N566513.98 49.6' Middle Half= E1443535.73, N567074.08 48.9' Right Outside Quarter= E1443319.10, N567229.70 48.4'							